**BAYONNE BARREL & DRUM** 

**REPORT#** 

61

**O.S.C.** 

JOE COSENTINO

DATE:

12/16/94

R.M.

M.R.ELLIS

DESCRIPTION OF DELIVERY ORDER: Mobilize necessary personnel and equipment to facilitate removal action. Overpack, sample, haz-cat drummed waste on site, to include storage tanks above & below ground, pits, gutters, courtyard and ash/soil piles. Proceed with T & D of drummed waste, rubber, ash/soils and drums related to shredding operations. Further provide any additional support needed to assist with the site removal per the O.S.C.

**LOCATION OF WORK:** 

150 RAYMOND BLVD. NEWARK, NJ 07105

**WEATHER:** 

Cloudy

**TEMPERATURE:** 

40

### **WORK PERFORMED TODAY BY OHM:**

- \* Continued the drum shredding operations today, further separating drums that contain labels Hazardous Waste " and any other legible manufacturers labels. Weston TAT documents all labels found with this information.
- \* By the days end the crew has completed shredding of 641 drums, additionally performed general cleanup of the area. Decon waters generated from the mask wash is drummed and staged inside the building # 1.

# **SUBCONTRACTOR SERVICES PERFORMED:**

- \* McRoberts Security, discuss and arrange for holiday coverage.
- \* Duffy Fuel deliver fuel today.

## **EXCEPTIONS / UNUSUAL CONDITIONS:**

\* At 0655 hrs. this morning, it is observed that a blue Lincoln town car was parked in front of the gate in, further a fire was going to the right side of the car. Security Guard on site failed to see what was going on, it was apparent that the fire was going for a while, burned was a large truck tire with other debris, the fire was distinguished and the police where called to remove the car. At approximately 0930 hrs. three men came to site to try and fix the car. The security company is notified, George Willis, he is informed of the matter, it would appear as though the guard was sleeping, therefore would explain why he did not see the fire or the car.

Because this same guard has been seen and caught sleeping three various times before, we have a good reason to believe that he was sleeping again when all this was going on. I am assured that this guard will be rotated and will not be allowed back on site again.

CHANGE IN METHOD OR SCOPE, SPECIFIC DIRECTION RECEIVED FROM O.S.C.:

### **DOCUMENTS SUBMITTED:**

#### **COMMENTS:**

